MSPO2530-4:2013

CERTIFICATION AUDIT SUMMARY REPORT

☐ INITIAL CERTIFICATION	⋈ SURVEILLANCE YEAR 01 CYCLE 2
☐ SURVEILLANCE YEAR 02	☐ SURVEILLANCE YEAR 03
☐ SURVEILLANCE YEAR 04	□ RECERTIFICATION

BBC PALM OIL MILL SDN BHD

(Reg. No. 906961-T)

Main Office Address: Lot 16433, Junction 5 Commercial Centre, Mile 5, Jalan Tun Hussein Onn, 97000 Bintulu, Sarawak

Site Address: Lot 20, Block 44, Sungai Segan, Kemena Land District, 97000 Bintulu, Sarawak

Certification Body:



KEBAL Resources Sdn Bhd

Sublot 7, No. 387, Lot 17821, 2nd Floor, Star Point Angle Commercial Centre, Jalan Stutong, 93350, Kuching, Sarawak

Tel: 082 287 288 Mobile: 017 713 8188

Email: kebalresource@gmail.com

Website: www.kebalresources.com.my

CLIENT ID: KRMC22.2

CERTIFICATION AUDIT SUMMARY REPORT

CERTIFIED ENTITY: INFORMATION

Company Name:	BBC Palm Oil Mill Sdn Bhd			
Main Address:	Lot 16433, Junction 5 Commercial Centre, Mile 5, Jalan Tun Hussein Onn, 97000 Bintulu,			
	Sarawak			
Site Address:	Lot 20, Block 44, Sungai Se	egan, Kemena Land Dis	strict, 97000 Bintulu, Sarawak	
Contact Person:	Name:	Designation:	Contact No. & Address:	
	Raymond Lau Ben Fang	Mill Manager	019 8654469	
			raymond.lau@bbcgroup.com.my	
	Mohamad Firdaus b.	Compliance	012 8814524	
	Ibrahim	Manager	mohamad.firdaus@bbcgroup.com.my	
Registration No:	906961 - T	Report Ref No:	KRMC22.21023	
MPOB License No:	5748 2500 4000	Expiry Date:	31 07 2025	
Audit Scope:	Sustainable Management of Palm Oil Mill with Production Capacity of 60MT/Hour			
Scope of Activity:	Menjual dan Mengalih Fresh Fruit Bunches (FFB), Palm Kernel (PK), Crude			
	Palm Oil (CPO) & Sludge Palm Oil (SPO).			
	2. Membeli Dan Men	Value Dagatinges		
	3. Menyimpan Palm	Kernel (PK), Crude Pa	lm Oil (CPO) & Sludge Palm Oil (SPO).	
	4. Mengilang Fresh F	Fruit Bunches (FFB).		
No of Mill:	One (1)	Mill Output	60 MT/HR	
		Capacity:		
Standards:	⊠ MS2530-4:2013 Part 4:	General principles fo	r palm oil mills	
Certification Type:	⊠ Individual	Audit Stage:	⊠ Surveillance 01 Cycle 2	
Certificate No:	KRMC22.21124	Date Issue:	26 12 2024	
1st Certification Cycle:	01 01 2019 – 31 12 2023	2 nd Certification C	Sycle: 01 01 2024 – 31 12 2028	

Report Updated on:	09 12 2024

MALAYSIAN SUSTAINABLE PALM OIL [MSPO CERTIFICATION]

FIVE YEARS AUDIT PROGRAMME

1. SURVEILLANCE 1 Cycle 2

Not more than 12 months from Certification Decision Date

Certification Stage:	Surveillance Audit 1 [MS 2530: 4: 2013]			
Plan Audit Date:	November 2024	ber 2024 Actual Audit Date: 11 - 12 11 2		
Lead Auditor:	Martin Kusong	Certifier:	Maxwell S. Landong	
Peer Reviewer 1:	Not applicable	Peer Reviewer 2:	Not applicable	

2. SURVEILLANCE 2 Cycle 2

Not more than 12 months after Surveillance 1

Certification Stage:	Surveillance Audit	2 [MS 2	530: 4-1: 2022]	
Plan Audit Date:	November 2025		Actual Audit Date:	00 00 0000
Lead Auditor:	To be appointed		Certifier:	To be appointed
Peer Reviewer 1:	Not applicable	1 n	Peer Reviewer 2:	Not applicable
Kebal Kesources				

3. SURVEILLANCE 3 Cycle 2


Not more than 12 months after Surveillance 2

Certification Stage:	Surveillance Audit 3 [MS 2530: 4-1: 2022]		
Plan Audit Date:	November 2026	Actual Audit Date:	00 00 0000
Lead Auditor:	To be appointed	Certifier:	To be appointed
Peer Reviewer 1:	Not applicable	Peer Reviewer 2:	Not applicable

4. SURVEILLANCE 4 Cycle 2

Not more than 12 months after Surveillance 3

2530: 4-1: 2022]



Plan Audit Date:	October 2027	Actual Audit Dat	e 00 00 0000
Lead Auditor:	To be appointed	Certifier:	To be appointed
Peer Reviewer 1:	Not applicable	Peer Reviewer 2:	Not applicable

5. RECERTIFICATION / REASSESSMENT Cycle 3

4 Months before Certificate Expiry Date

Certification Stage:	Recertification / Reassessment Audit [MS 2530: 4-1: 2022]			
Plan Audit Date:	October 2028 Actual Audit Date 00 00 0000			
Lead Auditor:	To be appointed	Certifier:	To be appointed	
Peer Reviewer 1:	To be appointed	Peer Reviewer 2:	To be appointed	



TABLE OF CONTENTS

NO	DESCRIPTION	PAGES
	AUDIT INFORMATION	6
	REPORT REVIEW	7
1.	INTRODUCTION	8 – 9
1.1.	LOCATION MAP OF THE PRODUCTION UNIT	10 – 11
1.2.	AUDIT OBJECTIVES	11
1.3.	AUDIT CRITERIA	12
2.	SCOPE OF CERTIFICATION	12
3.	EXISTING CERTIFICATION	12
4.	AUDIT METHOD AND PROGRAMME Kebal Resources	12 – 13
5.	ASSESSMENT FINDINGS	13 – 14
6.	PREVIOUS AUDIT FINDINGS – [IF APPLICABLE]	15
7.	STAKEHOLDERS CONSULTATION	15
8.	AUDIT SUMMARY AND RECOMMENDATION	15
9.	PEER REVIEWERS' DECISION	15
10.	REPORT REVIEW BY CLIENT / AUDITEE	15 – 16
11.	CERTIFICATION DECISION PANEL	16
12.	MSPO CERTIFICATION ISSUANCE	16

AUDIT INFORMATION

SURVEILLANCE AUDIT 1 C	YCLE 2		
Date of Audit:	11 – 12 th November 2024		
Audit Role:	Lead Auditor		
Name:	Martin Kusong		
Qualifications:	 Bachelor in Agricultural Science UPM, Corporate MBA UNIMAS Successfully completed the following courses and passed the examinations: MSPO Lead Auditor Course October 2017 & March 2022 Lead Auditor Integrated Management System (IMS) ISO 9001, ISO 14001 & ISO 45001 in April 2022 Lead Auditor Course ISO/IEC 17065:2012 Jan/Feb 2024 Exemplar Global Certified ISO 9001:2015 Quality Management System Lead Auditor Course in May 2024 Workshop Best Practices in Social Impact Assessment in March 2022 Qualified Planter more than 30 years of experience in oil palm industry as Plantation Manager with Statutory Body [SALCRA] 		
MSPO Auditing Experience:	Clocked in 90.5 mandays as Trainee auditor, Auditor & Lead Auditor		
Audit Role:	Auditor Resources		
Name:	Duke Ladin Sebang		
Qualifications:	 Bemidji State Univ, Minnesota, USA – Bac. of Sci. in Business Admin. (1999) & Bac. of arts (Hons) in Management OUM (2017) Successfully completed the following course: MSPO MS 2530:2015 in April 2019 IMS ISO9001 QMS, ISO14001 EMS & ISO45001 OSHMS in November 2022 MSPO Lead Auditor MS2530:2022 in April 2024 Exemplar Global Certified ISO 9001:2015 QMS Lead Auditor MS2530:2022 in June 2024 		
MSPO Auditing Experience:	Clocked in more than 100 mandays as Trainee auditor and Auditor		

CLIENT ID: KRMC22.2

REPORT REVIEW:	:
----------------	---

PEER REVIEWER 1 [Applicable for Stage 2 and Recertification Dated: 00 00 0000									
Audit only]									
Name:						Position:			
Contact No:						Email:			
Qualifications					<u> </u>				
MSPO experience & e	xpertise:								
	l								
PEER REVIEWER 2 [A	pplicable	for Stag	e 2 and	Rece	ertification		Dated: 00 00 0000		
Audit only]									
Name:						Position:			
Contact No:						Email:			
Qualifications									
MSPO experience & e	xpertise:								
CLIENT REVIEW							Dated: 19 12 2024		
Name:	Mohamad	d Firdaus	B. Ibral	him	Position	: Complian	ce Manager		
Contact No:	012 8814524 Keba			R	esoEmail	mohamad	mohamad.firdaus@bbcgroup.com.my		
CERTIFICATION DEC	ISION PA	NEL					Dated: 20 12 2024		
Certifier:	Maxwell	S. Lando	ng			Designation:	Certification Director		
Signature:									
· M 810									
REPORT APPROVAL							Dated: 23 12 2024		
<u> </u>	Leroy Wil	lfred Lan	dong			Designation:			
Signature:	2,	1/							
. J	3	5							

CLIENT ID: KRMC22.2

SUMMARY REPORT

1.	INTRODUCTION					
	This report presents the results of the Certification Assessment carried out by Kebal Resources Sdn					
	Bhd as per below:					
	Company Name:	BBC Palm Oil Mill Sdn Bhd [BBCPOM]				
	Location:	Lot 20, Block 44, Sungai Segan, Kemena Land District, 97000 Bintulu,				
		Sarawak				
	Date:	11 – 12 th November 2024				
	The purpose was to assess the operations of BBCPOM against the requirements of the Malaysia					
	Sustainable Palm Oil (MSPO) certifications.					
	ORGANIZATION B	RIEF				

BBCPOM is owned by BBC Group, a conglomerate organization headquartered in Bintulu Sarawak. Along with BBC group of Oil Palm Plantations, BBC Palm Oil Mill Sdn Bhd was initially certified under MS2530-4:2013 on 1st January, 2019; under a 5-year Certification Cycle with validity period from 01 01 2019 to 31 12 2023

Recertification Audit of BBCPOM to continue and maintain its MSPO Certification under 2nd 5 - year Certification Cycle was conducted on 11 – 12th December 2023 with validity period from 01 01 2024 to 31 12 2028 under the Standard MS2530-4:2013.

The Surveillance Audit 1 Cycle 2 was conducted on 11 & 12th November 2024; two (2) auditors were assigned to do the assessment. One and a half (1½) days for each auditor or a total of 3 mandays required to complete the audit.

BBCPOM is sited at Lot 20, Block 44, Sungai Segan, Kemena Land District, 97000 Bintulu, Sarawak; approximately 16 km and 30 minutes driving distance from Bintulu Town Centre; GPS Geo coordinates N3.064526, E113.069599.

The assessment method follows principles of 3P (Paper, Practice & People). This certification assessment is a sampling process where management systems effectiveness & efficiency are confirmed via an Audit Trail that the Auditor established to make an accurate conclusion.

Assessments were conducted at Mill Site Office, Mill sites & facilities, staff & workers quarters, Mill operations. Information & data were systematically gathered & documented from interviews, observations of process and activities, field audits & review of documentations and records. To

 $Sublot\ 7,\ No.\ 387,\ Lot\ 17821,\ 2^{nd}\ Floor,\ Star\ Point\ Angle\ Commercial\ Centre,\ Jalan\ Stutong,\ 93350,\ Kuching,\ Sarawak.$

Issue 1: 01 07 2021

KEBAL RESOURCES SDN BHD [1398498-T]



CERTIFICATION AUDIT SUMMARY REPORT

KRSB-MSPO-CASR-F15

CLIENT: BBC PALM OIL MILL SDB BHD

CLIENT ID: KRMC22.2


ensure thoroughness in the Field Audits a 28-point Field Audit Checklists form was used to document and determine the Auditors findings.

Mill employees are remunerated well above minimum wage; and living & housing conditions in the Mill Staff & Workers Quarters meet the requirements of health & safety regulations & the minimum housing standard. Available amenities in BBCPOM include treated water, domestic waste collection & disposal, electricity and telecommunication services. Local communities who are suitably qualified are given priority to work at the Mill.

Findings: There was one (1) finding [OFI] during this Surveillance Audit 1 Cycle 2. It was evidenced that BBCPOM has complied & conformed to MSPO Certification standards, conditions & requirements. BBCPOM had appointed dedicated personnel responsible for administration of MSPO and other Certification Standards. At BBC HQ, the Compliance Manager oversees the implementation of requirements of MSPO and other Standards as well.

In conclusion, the Audit Team therefore recommended that BBCPOM Surveillance Audit 1 Cycle 2 under MSPO Standards MS2530-4:2013 (Part 4 – General Principles for Palm Oil Mills) be maintained.

Kebal Resources



KRSB-MSPO-CASR-F15

CLIENT ID: KRMC22.2


1.1. LOCATION MAP OF THE PRODUCTION UNIT [Location, Plantation Areas, Division/Sub-Division]

Google Location Map Geo - coordinates: N3.064526, E113.069599



CLIENT ID: KRMC22.2

BBC Palm Oil Mill Sdn Bhd Perimeter Map



1.2.	AUDIT OBJECTIVES					
	a. To confirm that the management system conforms with all the requirements of the MSPO					
	standard;					
	b. To confirm that the organization has effectively implemented the planned MSPO					
	management system;					
	c. To confirm that the management system is capable of achieving the organization's policy					
	objectives.					

Sublot 7, No. 387, Lot 17821, 2nd Floor, Star Point Angle Commercial Centre, Jalan Stutong, 93350, Kuching, Sarawak.

CLIENT ID: KRMC22.2

1.3.	AUDIT CRITERIA						
	The criteria of this audit is based on the MSPO Scheme Requirements and Standards:						
	□MS2530-2:2013		□MS2530-3:2013		⊠ MS2	⊠ MS2530-4:2013	
	<u> </u>						
TABLE 1: FFB PROCESSED VOLUME (MT)							
Year			2023			2024	
Projecti	ion (MT)		300,000		300,000		
Actual \	Volume (MT)		294,476		245,03	35 (Mar-Dec 2023)	
Estimate	ed volume of CPO produ	ced based	on previous Fin	ancial Year perfo	rmance.		
2.	SCOPE OF CERTIFICA	ATION					
	The scope of this asses	ssment is	the following ope	rations of BBC P	alm Oil M	ill Sdn Bhd.	
	SCOPE						
	Sustainable Management of Palm Oil Mill with Production Capacity of 60MT/Hour						
	PROPOSED AMENDED SCOPE [if applicable]						
	No change						
3.	EXISTING CERTIFICATION [if applicable]						
	This is TRANSFERED CERTIFICATION from BQAS Certification Sdn Bhd. Transfer of Certification was						
	conducted according to KRSB-QP M18 Procedure [Transfer of Accredited Certification of						
	Management Systems]. Kebal Resources Sdn Bhd was appointed as Certification Body to conduct						
	Recertificatio & subsequent Surveillance 1 to 4 under the MSPO 2nd Certification Cycle.This						
	Surveillance Audit 1 Cycle 2 is conducted under MSPO MS2530-4:2013.						
	Current Certification (Please tick the certification you are currently certified)						
	□ ISO 9001	□ ISO 9001 □ EMS 1		☐ ISO 45001		☐ ISO 22001	
	☐ HACCP ☐ RSPO			□ ISCC		⊠ sccs	
	1			<u> </u>			
4.	4. AUDIT METHOD AND PROGRAMME						
	The audit was conducted in one and half (11/2) audit days and involving a single site of BBC Palm Oil						
	Mill Sdn Bhd. The audit covers documentation review for internal procedures, management system,						

Sublot 7, No. 387, Lot 17821, 2nd Floor, Star Point Angle Commercial Centre, Jalan Stutong, 93350, Kuching, Sarawak.

Tel: +6 082 287 288

KEBAL RESOURCES SDN BHD [1398498-T]



CERTIFICATION AUDIT SUMMARY REPORT

KRSB-MSPO-CASR-F15

CLIENT: BBC PALM OIL MILL SDB BHD

CLIENT ID: KRMC22.2

mill processing inspection as well as identification of any significant issues for both environment or social issues.

The audit evidence obtained was based on a sample of the information; thereby introducing an element of uncertainty. The methodology for objective evidence collection included physical site inspection, observation of tasks and processes, interview with workers and stakeholders, documentation review and monitoring data.

SITE SAMPLING [for group certification, outsourcing]

Not applicable as BBC Palm Oil Mill Sdn Bhd is a single site

ASSESSMENT FINDINGS

One (1) finding found in this Surveillance Audit 1 Cycle 2.

Surveillance Audit 1 Cycle 2: Summary of Findings by Principle & Requirement

Principle	Requirement	Compliance	
rillicipie	Kequirement	Yes	No
1.0	Management commitments & responsibilities		
1.1	Malaysian Sustainable Palm Oil (MSPO) Policy	×	
1.2	Internal audit	⊠	
1.3	Management review Kebal Resources	⊠	
1.4	Continual Improvement	⊠	
2.0	Transparency		
2.1	Transparency of information and documents relevant to MSPO requirements	×	
2.2	Transparent method of communication and consultation	⊠	
2.3	Traceability	⊠	
3.0	Compliance to legal requirements		
3.1	Regulatory requirements	⊠	
3.2	Land use rights	⊠	
3.3	Customary land rights	⊠	
4.0	Social responsibility, health, safety and employment condition		
4.1	Social Impact Assessment (SIA)		×



KEBAL RESOURCES SDN BHD [1398498-T]

CERTIFICATION AUDIT SUMMARY REPORT

KRSB-MSPO-CASR-F15

CLIENT: BBC PALM OIL MILL SDB BHD


CLIENT ID: KRMC22.2

4.2	Complaints and grievances	×			
4.3	Commitment to contribute to local sustainable development	×			
4.4	Employees' safety and health				
4.5	Employment conditions	×			
4.6	Training and competency	×			
5.0	Environment, natural resources, biodiversity and ecosystem services				
5.1	Environmental management plan	×			
5.2	Efficiency of energy use and use of renewable energy	×			
5.3	Waste management and disposal	×			
5.4	Reduction of pollution and emission	×			
6.0	Best practices				
6.1	Mill Management	×			
6.2	Economic and financial viability plan	×			
6.3	Transparent and fair price dealing	⊠			
6.4	Contractor	⊠			
	In conclusion, based on the audit, it was apparent that:		J		
a)	The internal audit program has been fully implemented and demonstrates effectiveness as a tool for maintaining and improving the management system				
b)	The management review process is adequate and effective.				
c)	The organization has met its objectives and targets and monitored progress towards their achievement.				
d)	The management system documentation confirms with the requirements of the MSPO audit standard.	×			
	-				

KRSB-MSPO-CASR-F15

CLIENT ID: KRMC22.2

6.	PREV	PREVIOUS AUDIT FINDINGS [if applicable]				
				<u> </u>		
\boxtimes	All the MSPO Standard requirements are complied with [No findings]					
	Nonconformity identified during previous audits has been corrected and the corrective action					
	continues to be effective					
	Not ac	dequately addressed	d nonconformity ic	lentified during previous audit activities and the specific		
	issue	has been re-defined	d in the nonconfor	mity section of this report.		
	1					
7.	STAK	EHOLDERS CONS	ULTATION [Appl	icable to Stage 2 & Recertification Audit]		
	Not a	oplicable				
	1					
8.	AUDI	T SUMMARY AND	RECOMMENDAT	ION		
	The a	udit team conclude	s that the organiza	ation fulfilled the requirements of the MS 2530-4:2013		
	standard and demonstrated the ability of the system to systematically achieve agreed requirements					
	for products or services within the scope and the organization's policy and objectives.					
	The audit team recommends that, MSPO certification be maintained to BBC Palm Oil Mill Sdn					
	Bhd.					
9.	PEER REVIEWER'S DECISION [Applicable to Stage 2 & Recertification Audit]					
	Not a	oplicable	Kebal R	esources		
10.	REPORT REVIEW BY CLIENT / AUDITEE					
Excerpts	:					
To:	The Executive Chairman, Kebal Resources Sdn Bhd					
From	: Mohamad Firdaus B. Ibrahim					
CLIENT F	NT REVIEW REPORT			Date of review: 19 12 2024		
Reviewer			Designation: Compliance Manager			
This is to confirm that we have reviewed the Certificat			ved the Certification	on Audit Summary Report with the following conclusion.		
a)	\boxtimes	We are satisfied w	ith the adequacy,	contents & accuracy of the Report and have no further		
´	ic)	inputs or feedback				
b)		We are satisfied with the adequacy, contents & accuracy of the Report. However, we wish				
]	to add our inputs / feedback as follows: NIL				



KEBAL RESOURCES SDN BHD [1398498-T]

CERTIFICATION AUDIT SUMMARY REPORT

KRSB-MSPO-CASR-F15

Date: 19 12 2024

CLIENT: BBC PALM OIL MILL SDB BHD

CLIENT ID: KRMC22.2

c)

We are not generally satisfied with the Report; and our comments / inputs / feedbacks are as follows: NIL

Cars.

Mohamad Firdaus B. Ibrahim

Compliance Manager

11. CERTIFICATION DECISION PANEL

CERTIFIER DECISION PANEL

I, the undersigned, being the Certifier, confirm that I have reviewed the Audit Package and examined thoroughly all contents of the Report in its' entirety, including the incorporation of Peer Review comments/report and other related reports [where applicable and relevant].

I confirm that, to the best of my knowledge the information and conclusions included in this report have been prepared in compliance with the Standards requirements; and done in good faith and that the certification decision had been based upon this information.

I, hereby confirm that, BBC PALM OIL MILL SDN BHD be MAINTAINED the MSPO Certificate under the Standard MSPO2530-4:2013 [Part 4: General Principles for Palm Oil Mills].

Mena

Maxwell S. Landong

Date: 20 12 2024

12. MSPO CERTIFICATE ISSUANCE

MSPO Certificate No **KRMC22.2.1124** for BBC PALM OIL MILL SDN BHD under Malaysian Sustainable Palm Oil [MSPO] **MS 2530-4:2013**, **Issue 3** will be issued on **01 01 2025** (anniversary date) with validity period from **01 01 2024 to 31 12 2028**.

-END OF REPORT-

 $Sublot\ 7,\ No.\ 387,\ Lot\ 17821,\ 2^{nd}\ Floor,\ Star\ Point\ Angle\ Commercial\ Centre,\ Jalan\ Stutong,\ 93350,\ Kuching,\ Sarawak.$

Mobile: +6 017 713 8188